




Version	Created: 10/11/2025
V2	Measured: 01/11/2016

1545 Carling Avenue  
Ottawa, Ontario, Canada  
**Suite 308**

Please Refer to the Corresponding  
BOMA Method



This work product has been prepared by Extreme Measures Inc. pursuant to a contract with the Client for the sole benefit of and use by the Client. No third party may rely on this work product without the receipt of a reliance letter from Extreme Measures Inc.

This work product or portions thereof relies upon information provided by the Client and/or from third parties introduced by the Client that has not been independently verified by Extreme Measures Inc. Extreme Measures Inc. is not liable for any errors, omissions or inaccuracies that may result from such information.

